

**HARPER COUNTY ROAD & BRIDGE**  
**Weekly County Commission Report**  
March 14-18, 2016

**KENT STONEBRAKER-EAST FOREMAN**

1. Excavator 635 installing x-pipe & spreading shale on Rd 751-B. Trucks 305 & 310 hauling sand & shale to x-pipe on Rd 751-B. Graders patrolling.
2. Excavator 635 installing x-pipe & spreading shale on Rd 751-B. Trucks 305 & 310 hauling shale to x-pipe on Rd 751-B. Help flag traffic while Terracon takes core samples on the Danville blacktop. Graders patrolling.
3. Excavator 635 doing ditch work along Rd 668-23. Dozer 627 ripping shale at Plumb Thicket Landfill. Trucks 305 & 310 hauling shale to new x-pipe on Rd 751-B. Graders patrolling.
4. Excavator 635 & Grader 256 doing ditch work along Rd 668-23. Trucks 216, 305 & 310 hauling shale to new x-pipe on Rd 751-B. Trucks 216, 305 & 310 hauling shale to soft spots on Rd's 751-B & 664-21. Truck 305 hauling shale to field entrance on Rd 755-O. Graders patrolling.
5. Excavator 635 & Grader 256 doing ditch work along Rd 668-23. Dozer 627 ripping shale at Plumb Thicket Landfill. Truck 305 hauling shale to Rd 704-25.

**JIM THOMPSON-SHOP FOREMAN**

1. #216 2006 Sterling Truck, rear brake job. #607 2006 Mack Truck, coolant leak. #122 CAT 938K, sos motor.
2. #607 2006 Mack Truck, checked for coolant leak.
3. #216 2006 Sterling Truck, finished rear brake job. #607 2006 Mack Truck, coolant leak repairs.
4. #607 2006 Mack Truck, replaced hose filled with coolant. #251 JD Tractor, replaced battery.
5. #310 2006 Sterling Truck, service job-220,335 miles.

**LAWRENCE SMITH-WEST FOREMAN**

Loader 122 removing & chainsaws cutting trees in ditches & along Rd's 664-12, 715-D & 688-3. Reset signs on Rd's 725-H & I, 721-B & 688-3. Graders patrolling & spreading shale. Fixed & changed tires on trucks & belly dump trailers. Dozer 628 ripping & stockpiling shale at Stark Pit. Excavator 632 helping Bridge Crew at Bridge 674-9 #2. Loader 122 digging out & Trucks 118, 120, 124 & 607 hauling shale to soft & low spots on Rd's 688-4, 721-Y, Z & AA & 704-5 & 9. Flagging for Terracon on Rd's 715-W through AA.

**JEFF NULIK-BRIDGE FOREMAN**

1. Layout piling locations & drive 2-piling at Bridge 674-9 #2. Repairs to hammer & follow cap on crane.
2. Drive 3-piling, shoot, mark cutoff & cut to height. Make barricade stakes.
3. Grind piling. Set bearing plates & cap-tack weld. Dig out wing walls at Bridge 674-9 #2.
4. Measure, cut & add 7" to 20' stick of 8" channel iron. Measure, cut & install whaler. Measure, lay out & weld stringer tie downs. Drive 4-wing wall piling in place at Bridge 674-9 #2.
5. Reset stringer for west span & tie down to bulkhead. Install west wing wall supports at Bridge 674-9 #2.